

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/30SESW

Location ID: 335670

Date: 10/8/2024



Location Entrance – Photo #04024



Wellheads – Photo #04026

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/30SESW

Location ID: 335670

Date: 10/8/2024



Gas Meters – Photo #04031



Gas Lift – Photo #04025

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/30SESW

Location ID: 335670

Date: 10/8/2024



Tank Battery – Photo #04029



Open-Ended Line – Photo #04032

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/30SESW

Location ID: 335670

Date: 10/8/2024



Unserviceable Wildlife Screen – Photo #04035



Insufficient Erosion Control – Photo #04033

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/30SESW

Location ID: 335670

Date: 10/8/2024



Insufficient Erosion Control – Photo #04034