

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3844 From entrance to location




Photo # 3845 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3846 Location



Photo # 3847 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3848 Location

Photo # 3849 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3850 Location



Photo # 3851 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3852 Location



Photo # 3853 RWF 42-18 wellhead sign peeling & some info starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3854 RWF 543-18 wellhead sign peeling & some info starting to become illegible



Photo # 3855 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3856 Debris



Photo # 3857 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3858 Debris



Photo # 3859 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3860 Debris



Photo # 3861 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 3862 Holes in secondary containment liner/liner needs maintenance



Photo # 3863 Hole in secondary containment liner/liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Oct 8, 2024 at 10:57:54 AM
CO



Oct 8, 2024 at 10:57:34 AM
CO

Photo # 3864 Hole in secondary containment liner/liner needs maintenance

Photo # 3865 Hole in secondary containment liner/liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Oct 8, 2024 at 10:57:46 AM
CO

**Photo # 3866 Hole in secondary containment liner/liner
needs maintenance**