

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

10/02/2024

Document Number:

699700399

**FIELD INSPECTION FORM**Loc ID 423560 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10384

Name of Operator: GENESIS GAS &amp; OIL COLORADO LLC

Address: 1141 NORTH LOOP 1604 E 105-414

City: SAN ANTONIO State: TX Zip: 78232

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Cholas, Nick		nick.cholas@state.co.us	
Roberts, James		j75rober@blm.gov	BLM meeker

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423563	WELL	PR	11/01/2022	CBM	103-11880	CALAMITY RIDGE 14-31	EI

**General Comment:**

ECMC Environmental Inspection. All previous unresolved CAs for this location still apply to this inspection.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Unused equipment and trash and debris observed on location. See photos for details.		
Corrective Action:	Comply with Rule 606.		Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER		OTHER	STEEL AST		,
Comment:		Tank contents are unknown, tank label displays TEP Rocky Mountain LLC signage.			
Corrective Action:		Install sign to comply with Rule 605.h.			Date:

**Paint**Condition: Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient	Base Insufficient	Inadequate
Comment:		Various sizes of holes and tears in the liner of the tank battery secondary containment structure.		
Corrective Action:		Install liner material to ensure spill or released materials will be maintained with containment structure.		
		Date:		

**Venting:**Yes/No Comment: Corrective Action: Date: **Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

