

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2024

Submitted Date:

10/09/2024

Document Number:

696306802**FIELD INSPECTION FORM**Loc ID 424135 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10691Name of Operator: PHOENIX RESOURCES LLCAddress: 20165 NORTH 67TH AVENUE 122ACity: GLENDALE State: AZ Zip: 85308**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wolfe, Stephen		stephen.wolfe@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Gilliland, Harrison		phxresources1@aol.com	
Kelly, George	(888) 842-1090	phxresources@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424138	WELL	SI	07/01/2022	OW	123-33901	Siefkin 11-30H	SI

General Comment:[Follow-Up Inspection to FIR 696305330 dated 10.11.2023](#)

Location			
Lease Road:			
Type	Access		
comment:	Lease Road grown over with undesirable vegetation		
Corrective Action	Comply with Rule 606	Date:	11/11/2024
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	24-Hour Emergency Contact Number is not valid; see photos		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 11/11/2024
Good Housekeeping:			
Type	OTHER		
Comment:	Stained Soil at Gas Engine., Exhaust and Wellhead. See photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e		Date: 12/02/2022
Type	WEEDS		
Comment:	Weeds on Location. See photos		
Corrective Action:	Comply with Rule 606		Date: 12/02/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Propane Tank - 1000 Gallon		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Rupture Pin Valve is leaking with stained soils; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e		Date: 11/11/2024
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		Shares berm with the Crude Oil Tanks					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	500 BBLs	HEATED STEEL AST		40.552010,-104.258010		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<u>Flaring:</u>							
Type	Field Flare						
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	424138	Type:	WELL	API Number:	123-33901	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:		<div>SI - Since 07.01.2022. No MIT on File Shut-In at the time of this Inspection. No Production has been Repored since 07.01.2022</div>							
Corrective Action:		<div>Comply with 417.b Report Production on Form 7 per 413 Rules</div>					Date:		
BradenHead									
Date of Last Brhd Test:		12/20/2021		Annual Brhd Completed?		No			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:		NONE	
		End Surf Csg Pressure:		0					
Comment:		<div>No current Form 17 on File. Last Form 17 on File is from 12.22.2021</div>							
Corrective Action:		<div>Perform Bradenhead Test and Submit Form 17 per Rule 419.b(4)A</div>					Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									

Comment	User	Date
<p>On Thursday 10/01/2024 at approximately 14:13, I, Inspector Erica Petrie, conducted an a Follow-Up Field Inspection at Phoenix Resources LLS, Cass Farms 11-25H, Location #424135 in Weld County, Colorado.</p> <p>While there, I observed Production Operations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds on Entire Location; see photos. Comply with Rule 606. Orinigal Corrective Action Date of 12.02.2022 remains the same</p> <p>Stained Soil at Gas Engine., Exhaust and Wellhead. See photos. Comply with Rules 905.e. and 608.e. Orinigal Corrective Action Date of 12.02.2022 remains the same</p> <p>No current Production Reported. Last Production reported on 07.01.2022. Report Production on Form 7 per 413 Rules.</p> <p>No current Form 17 Bradenhead Test on File. Last Form 17 on File 12.22.2021. Perform Bradenhead Test and Submit Form 17 per Rule 419.b(4)A</p> <p>New Corrective Actions</p> <p>Well appears to have been Shut-In since 07.01.2022, two years have passed from initial shut-in date. No current MIT on File. Comply with Rule 417.b</p> <p>Rupture Pin Valve at Gas Sales Meter is leaking with Stained Soil; see photos. Comply with Rules 905.e. and 608.e. Corrective Action Date 11.11.2024</p> <p>Weeds on Lease Road; see photos. Comply with Rule 606. Corrective Action Date 11.11.2024</p> <p>24-Hour Emergency Contact Number is invalid; see photos. Install sign to comply with Rule 605.e. Corrective Action Date 11.11.2024</p>	petrie	10/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306803	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739789