

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2024

Submitted Date:

10/09/2024

Document Number:

696306804

FIELD INSPECTION FORMLoc ID 420717 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 20165 NORTH 67TH AVENUE 122A

City: GLENDALE State: AZ Zip: 85308

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Kelly, George	(888) 842-1090	phxresources@aol.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Gilliland, Harrison		phxresources1@aol.com	
Wolfe, Stephen		stephen.wolfe@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420712	WELL	PR	07/01/2022	OW	123-32689	Cass Farms 11-9H	PR

General Comment:

Follow-Up Inspection to FIR 696305332 dated 10.11.2023

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24-Hour Emergency Contact Number not valid; see photos

Corrective Action: Install sign to comply with Rule 605.e.

Date: 11/11/2024

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at Wellhead and Pumping Unit; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	10/26/2022
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Electrical Panels on West Side of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	10/27/2023
Type	WEEDS		
Comment:	Weeds on Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	10/26/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Appears to be plumbed to surface	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Electric Motor	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	500 BBLS	HEATED STEEL AST		40.594160,-104.334260
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Field Flare	
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 420712 Type: WELL API Number: 123-32689 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI - Shut-In at the time of this Inspection.
No Production has been Repored since 07.01.2022Corrective Action: Report Production on Form 7 per 413 Rules

Date: _____

BradenHeadDate of Last Brhd Test: 12/20/2021 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No current Form 17 on File. Last Form 17 on File is from 12.21.2021Corrective Action: Perform Bradenhead Test and Submit Form 17 per Rule 419.b(4)A

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>On Tuesday 10/01/2024 at approximately 14:43, I, Inspector Erica Petrie, conducted an a Follow-Up Field Inspection at Phoenix Resources LLS, Cass Farms 11-9H, Location #420717 in Weld County, Colorado.</u>	petriee	10/09/2024
<u>While there, I observed Production Operations.</u>		
<u>During this inspection the following possible compliance issues were observed:</u>		
<u>Weeds on Entire Location; see photos. Comply with Rule 606. Orinigal Corrective Action Date of 10.26.2022 remains the same</u>		
<u>Stained Soil at Wellhead and Pumping Unit; see photos. Orinigal Corrective Action Date of 10.26.2022 remains the same</u>		
<u>Unmarked Riser at Electrical Panels; see photos. Corrective Action Date of 10.27.2023</u>		
<u>No current Production Reported. Last Production reported on 07.01.2022. Report Production on Form 7 per 413 Rules.</u>		
<u>No current Form 17 Bradenhead Test on File. Last Form 17 on File 12.22.2021. Perform Bradenhead Test and Submit Form 17 per Rule 419.b(4)A</u>		
<u>New Corrective Action</u>		
<u>24-Hour Emergency Contact Number not valid; see photos. Install sign to comply with Rule 605.e. Corrective Action date 11.11.2024</u>		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306805	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739790