



Inspection Photos

Location Name: FLETCHER GULCH 34-41

Location ID: 316606

Inspection Date: September 24, 2024

Location sign, meter  
house.

Sep 24, 2024 12:34:00 PM  
+40.0934N -108.6098W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 34-41

Location ID: 316606

Inspection Date: September 24, 2024

Wellhead and  
compressor.

Sep 24, 2024 12:34:12 PM  
+40.0934N -108.6097W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: FLETCHER GULCH 34-41

Location ID: 316606

Inspection Date: September 24, 2024

Wellhead.



Sep 24, 2024 12:35:03 PM  
+40.0934N -108.6095W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: FLETCHER GULCH 34-41

Location ID: 316606

Inspection Date: September 24, 2024

Potentially impacted  
material adjacent to the  
compressor.

Sep 24, 2024 12:34:24 PM  
+40 0934N -108 6096W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: FLETCHER GULCH 34-41

Location ID: 316606

Inspection Date: September 24, 2024

Potentially impacted  
material adjacent to the  
compressor.

Sep 24, 2024 12:34:57 PM  
+40.0934N -108.6095W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: FLETCHER GULCH 34-41

Location ID: 316606

Inspection Date: September 24, 2024

Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105.

Sep 24, 2024 12:33:54 PM  
+40.0934N -108.6099W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources