

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2024

Submitted Date:

10/09/2024

Document Number:

715201026

FIELD INSPECTION FORMLoc ID 380893 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10791

Name of Operator: WAVETECH HELIUM INC

Address: 1801 BROADWAY SUITE 600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jobe, Patrick	(303) 534-3383	pjobe@wavetechenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208175	WELL	AP	06/28/2024	DA	017-07110	UPRC 1 Rosa 31-10	PR

General Comment:

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by road at location entrance		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No labeling on the tanks		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/02/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Weatherford 640		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	6 cyl Arrow motor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter run on east side of wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on west side of tanks inside berms		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry equipment, gas scrubber and propane tank		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	FIBERGLASS AST		39.029850,-102.211810	
Comment: 2-Production water tanks on the south side of the pumping unit						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Plastic lined berms					
Corrective Action:					Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
017-07110		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	208175	Type:	WELL	API Number:	017-07110	Status:	AP	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Ditches	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Berm on south side of location from location construction

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201053	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740050