



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/08/2024
Submitted Date:
10/09/2024
Document Number:
708302886

FIELD INSPECTION FORM

Loc ID
335674

Inspector Name:
Morris, Matthew

On-Site Inspection ☐

2A Doc Num:

Operator Information:

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
360	WELL	PR	09/20/2008	GW	045-15486	N. PARACHUTE EF12B-DX D31 59	PR
362	WELL	PR	09/21/2008	GW	045-15487	N. PARACHUTE EF11C D31 595	PR
292255	WELL	PR	09/17/2008	GW	045-14664	N. PARACHUTE EF 12A D31 595	PR
292256	WELL	PR	06/01/2018	GW	045-14663	N. PARACHUTE EF11D D31 595	PR
292258	WELL	PR	09/17/2008	GW	045-14665	N.PARACHUTE EF14B D31 595	PR
292259	WELL	PR	09/17/2008	GW	045-14661	N. PARACHUTE EF14A D31 595	PR
292260	WELL	PR	09/18/2008	GW	045-14660	N. PARACHUTE EF12D D31	PR
292261	WELL	PR	09/18/2008	GW	045-14659	N. PARACHUTE EF12C D31 595	PR

General Comment:

CECMC Inspection Report Summary

On 10/8/2024 at approximately 14:15, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/31NWNW at Location ID #335674 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Date Run: 10/9/2024 Doc [#708302886]

Page 1 of 6

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Chemical tanks, gas meters, and gas lift protected by concrete barriers.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 8		corrective date
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	CataDyne line heater		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:		Chemical tanks			
Corrective Action:				Date:	
Type: Gas Meter Run		# 8			
Comment:					
Corrective Action:				Date:	
<u>Venting:</u>					
Yes/No		NO			
Comment:					
Corrective Action:				Date:	
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities						
Facility ID:	360	Type:	WELL	API Number: 045-15486	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	362	Type:	WELL	API Number: 045-15487	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	292255	Type:	WELL	API Number: 045-14664	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	292256	Type:	WELL	API Number: 045-14663	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	292258	Type:	WELL	API Number: 045-14665	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	292259	Type:	WELL	API Number: 045-14661	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	292260	Type:	WELL	API Number: 045-14660	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	292261	Type:	WELL	API Number: 045-14659	Status: PR	Insp. Status: PR
Producing Well						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Other	Fail			Insufficient erosion control
		Gravel				
Gravel						
				Material Handling And Spill Prevention		
		Compaction	Fail			Rill erosion on access road
		Ditches				

Comment: Rill erosion on access road is bypassing ditch BMP.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/24/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302887	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740047