

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2024

Submitted Date:

10/09/2024

Document Number:

708904765

FIELD INSPECTION FORM

Loc ID: 324343 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 16 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280585	WELL	PR	07/01/2021	GW	045-11294	HMU 6-11 (J6SE)	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 10/09/2024 at approximately 14:49 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at QB Energy HMU 6-11 (J6SE) Pad. Location # 324343 in Garfield County Colorado.
 Please refer to inspection 708904507 conducted on 09/06/2024, previous corrective action has not been completed. Location is within High Priority/NSO/Black Bear Habitat areas. Location is approximately 140 yards from East Mamm Creek. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Signs/Marker - Wellhead lacks required signage/does not comply with CECMC rules with a CA date of 10/07/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Split pad/Remote location - Wellhead only, tank battery & separator located on the HMU 6-15A (J6SEB) location # 432265

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead lacks required signage/does not comply with CECMC rules		
Corrective Action:	Comply with CECMC wellhead signage rules		Date: 10/07/2024
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Jersey barriers around wellhead		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Pressure transducer located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 280585 Type: WELL API Number: 045-11294 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds						
		Compaction				Light compaction in some sections
Berms						
		Gravel				Sparse to none in sections
Check Dams						
		Ditches				
Culverts						
		Other				Mag chloride on some sections of lease road
Gravel						Sparse to none in some areas
Rip Rap						
Compaction						Light compaction in some areas
Ditches						
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker for corrective action	smelserw	10/09/2024
Split pad/Remote location - Wellhead only, tank battery & separator located on the HMU 6-15A (J6SEB) location # 432265		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904766	Inspection 708904765 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740136
708904767	Inspection 708904765 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740137