

Inspection Photos

Loc: 322234

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 10/9/2024

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast at the beginning of the access road. The access road has not been reclaimed.



Inspection Photos



Photo 2. Facing south toward the location. The well has been plugged and abandoned however final reclamation has not yet been completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 10/9/2024

Inspection Photos



Photo 3. Facing southwest along the fill slope. The location will need to be recontoured back to the original slopes



Inspection Photos



Photo 4. The electric utilities remain at the location and should have been removed with 3 months of abandonment. The entire powerline and poles servicing this location must be removed. There is a topsoil pile shown at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 10/9/2024

Inspection Photos



Photo 5. Facing toward the south side of the location. The tanks have been removed since the previous inspection.



Inspection Photos



Photo 6. There was previous impacts observed and there is oil stained soil shown at red arrow. The area of the tank battery and abandoned well need to be sample per form 27 decommissioning of the well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 10/9/2024

Inspection Photos



Photo 7. Facing southwest at the south side of the location. There is an erosion channel shown at red arrow which will need to be repaired and stabilized.



Inspection Photos



Photo 8. Facing south along the cut slope. There are rilling erosion along the cut slope which is not stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 10/9/2024

Inspection Photos



Photo 9. Facing northwest along the cut slope. There cut slope is not stabilized.



Inspection Photos



Photo 11. Facing south at the location standing from base of the cut slope.

