

Inspection Photos
Location Name: QB Energy Mamm Creek J6SEB Pad
Location #: 432265



Oct 9, 2024 at 3:00:30 PM



Oct 9, 2024 at 3:01:35 PM
CO

Photo # 4312 From entrance to location

Photo # 4313 Location

WELL NAME	API#	IANK#	LAT	LONG
HMU 6-11	0504511294	84768/84312/265400/84311	39.387656	-107.706611
HMU 6-12D	0504521939	84768/84312/265400/84311	39.387484	-107.706221
HMU 6-18D	0504521944	84768/84312/265400/84311	39.387387	-107.706099
HMU 6-15A	0504521936	84768/84312/265400/84311	39.387387	-107.706099
HMU 6-13AA	0504521937	84768/84312/265400/84311	39.387319	-107.706136
HMU 6-13A	0504521941	84768/84312/265400/84311	39.387349	-107.706139
HMU 6-15AA	0504521940	84768/84312/265400/84311	39.387319	-107.706049
HMU 6-13D	0504521943	84768/84312/265400/84311	39.387418	-107.706097
HMU 6-12DD	0504521942	84768/84312/265400/84311	39.387447	-107.706178
HMU 6-11A	0504521938	84768/84312/265400/84311	39.387469	-107.706179
KRK 6-10D	0504599085	84768/84312/265400/84311	39.47246	-107.70578

CAERUS Caerus Piceance LLC
South Piceance
J6SE 892
NWSE SEC-6 8S R92W
UNIT# COC55972E
LEASE# COC51156

ACCESS BY- COUNTY ROAD 315
IN CASE OF EMERGENCY DIAL
970-285-2615 OR 911

Inspection Photos
Location Name: QB Energy Mamm Creek J6SEB Pad
Location #: 432265



Photo # 4314 Location



Photo # 4315 Location

Inspection Photos
Location Name: QB Energy Mamm Creek J6SEB Pad
Location #: 432265



Photo # 4316 Location

Photo # 4317 Location

Inspection Photos
Location Name: QB Energy Mamm Creek J6SEB Pad
Location #: 432265



Photo # 4318 Location

Photo # 4319 Location

Inspection Photos
Location Name: QB Energy Mamm Creek J6SEB Pad
Location #: 432265



Photo # 4320 Location

Photo # 4321 Location

Inspection Photos
Location Name: QB Energy Mamm Creek J6SEB Pad
Location #: 432265



Photo # 4322 Insufficient wildlife protection for hole around wellhead/wildlife hazard

Photo # 4323 Insufficient wildlife protection for hole around wellhead/wildlife hazard

Inspection Photos
Location Name: QB Energy Mamm Creek J6SEB Pad
Location #: 432265



Photo # 4324 Insufficient wildlife protection for hole around wellhead/wildlife hazard

Photo # 4325 Unused tank rings in secondary containment