

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2024

Submitted Date:

10/04/2024

Document Number:

696206343**FIELD INSPECTION FORM**Loc ID 438499 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438499	LOCATION	AC			-	Piceance 28-11 Pad	RI

General Comment:

On 9/27/2024, Western Reclamation Work Lead Trujillo conducted an inspection at Laramie Energy LLC's Piceance/28-11 Pad Location in Mesa County, Colorado.

The following compliance issues were observed during this inspection:

- Spills
- Wildlife protections

Refer to the Location section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-897-6191 / 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Noxious (Canada Thistle, Musk thistle) weeds observed within the interim areas of the Location, and along the access road. Noxious weed management efforts by Operator also evident, though some weeds were observed to still be alive- ongoing weed management efforts will be required until Location receives a passing final inspection. A follow-up inspection will be conducted during a future growing season to evaluate compliance with 1003.f and 606.c requirements.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
Comment:	Fluids observed spilled within the trailered equipment's secondary containment measure; equipment currently connected to the separator equipment.			
Corrective Action:	Comply with Rule 912.a- remove/dispose fluids spilled within containment.			Date: 10/26/2024

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
-------	---	--	-----------------

Comment:	Wildlife protection measures at the 500 gal methanol tank (next to wells) has not been maintained in proper functioning condition.		
Corrective Action:	Comply with Rule 902.b- install or repair wildlife protection BMPs	Date:	10/26/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	3	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)	Produced water / condensate mix.				
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal				Adequate	
Comment:	Containment measure appeared to be in proper functioning condition at time of inspection.				
Corrective Action:					Date:

Venting:

Yes/No				
Comment:				
Corrective Action:				

Flaring:

Type				
Comment:				
Corrective Action:				

Inspected Facilities									
Facility ID:	438499	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: HAY MEADOW, IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? PassComment No waste or debris observed on the interim or production areas of the Location.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? PassComment No unused or unneeded equipment observed on the interim or production areas of the Location.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment Anchors not observed.

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced _____ Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? I

Comment Though there is approximately 1/2 acre on the west end of the well pad that does not appear to be necessary for production, no additional reclamation work is being required at this time; vegetation within the reclaimed areas of the Location appears to be progressing towards EMCM 1003 revegetation standards. Noxious weed issues observed throughout the interim (see good housekeeping).

Continue to monior and manage inteirm areas. Conduct work as necessary to ensure site progresses towards 1003 standards.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: HAY MEADOW, IRRIGATED

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains						Battery Location, southwest end of pad.
				Material Handling And Spill Prevention		Secondary containment, trailered equipment
Drains						Well pad, south end of pad.
Sediment Traps						Well pad, south end of pad.
Ditches						Perimeter of WPS
Sediment Traps						Battery Location, southwest end of pad.
Culverts						Location entrances (Well/Battery pad)
Gravel						
Compaction						

Comment:

No immediate stormwater issues observed at time of inspection.

Corrective Action:

Date:

Pits:

NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403946987	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6734059
696206344	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6734041