

# Inspection Photos

10/08/2024

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 335781

**Inspection Doc:** 696206367

Garfield County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



**Photo 1:** Photos taken from the north end of the western working pad surface, facing south. Operator appears to have performed grading operations to address tracking and stabilization concerns observed during the 3/15/2024 inspection. Unclear if additional controls were implemented to address the tracking and stabilization concerns; BMPs to stabilize the working pad surface, as well as to minimize tracking during wet conditions show sign of disrepair and/or do not appear sufficient; gravel is thin throughout the western pad; tracking is becoming evident. Maintenance advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



October 8, 2024



October 8, 2024

**Photo 2:** Photos taken from the access road, facing west. Photo shows erosion degradation due to stormwater runoff from the main lease road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



**Photo 3:** Photo example showing information on signs are peeling.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



**Photo 4:** Photos taken from the south end of the western pad, facing southwest and southeast. Photos examples showing additional reclamation efforts have been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



**Photo 5:** Photos 5-6 taken from the north end of the eastern pad. Photos provide an overview from east, southeast, southwest to west. Photo shows additional reclamation and contour work to address stormwater ponding issues have been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



**Photo 6:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



**Photo 7:** Examples of additional sediment traps implemented along the east end of the Location.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335781



**Photo 8:** Photos taken from west end of the eastern pad, facing north. Photo shows additional reclamation and contour work to address stormwater ponding issues have been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources