

# Interim Reclamation and Stormwater Inspection

September 10, 2024

Operator: FULCRUM ENERGY OPERATING # 10805

Location ID: 436801

Inspection Document #: 712300073

Jackson County, CO

Logan Maxwell  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Surprise Unit 2-08H  
Location ID: 436801



**Photo 1.** Photo taken from the entrance of Location. Photo illustrates the Location Operator sign.



**Photo 2.** Photo taken from the wellhead. Photo illustrates that API was added to well signage.



## Inspection Photos

Location Name: Surprise Unit 2-08H

Location ID: 436801



**Photo 3.** Photo taken from the eastern interim reclamation area, facing north. Photo illustrates topsoil stockpile, with weed growth (e.g., Russian Thistle) present and little to no perennial vegetation established. Silt fence was removed. Comply with 1002 Rules.



**Photo 4.** Photo taken from the eastern topsoil stockpile, facing south. Photo illustrates topsoil stockpile, with weed growth (e.g., Russian Thistle) present and little to no perennial vegetation established. Silt fence was removed.

Inspection Photos  
Location Name: Surprise Unit 2-08H  
Location ID: 436801



**Photo 5.** Photo taken 4/15/24 from the eastern interim reclamation area, facing southeast. Photo illustrates disturbances related to remediation project.



**Photo 6.** Photo taken from the eastern interim reclamation area, facing southeast. Photo illustrates that interim reclamation has not occurred along this portion of the pad. Comply with Rule 1003.

Inspection Photos  
Location Name: Surprise Unit 2-08H  
Location ID: 436801



**Photo 7.** Photo taken from the top of the topsoil stockpile, facing SW. Photo illustrates topsoil stockpile is not properly stabilized, with evidence of erosion. Comply with 1002.c.




**Photo 8.** Photo taken from the eastern portion of working pad surface area, facing SW. Photo illustrates that the sediment trap is not functioning properly. Comply with Rule 1002.f.



Inspection Photos  
Location Name: Surprise Unit 2-08H  
Location ID: 436801



**Photo 9.** Photo taken from the eastern working pad surface, facing west. Photo illustrates erosion downhill from sediment trap revegetation of the fill slopes are in process. Operator shall continue to monitor and manage until Location reaches 1003 standards.



**Photo 10.** Photo taken from the northern portion of interim area, facing east. Photo illustrates check dams are not functioning properly. It was observed that erosion (red arrows) and downhill sedimentation were occurring.

Inspection Photos  
Location Name: Surprise Unit 2-08H  
Location ID: 436801



**Photo 11.** Photo taken from the western working pad surface, facing east. Photo illustrates weeds at the wellhead.



**Photo 12.** Photo taken at the wellhead, facing southwest. Photo illustrates wildlife protection devices were missing from equipment. Comply with Rule 902.b.