

Interim Reclamation and Stormwater Inspection

September 10, 2024

Operator: WOODBURY RESOURCES LLC #10761

Location ID: 324766

Inspection Document #: 712300088

Jackson County, CO

Logan Maxwell
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fuqua 18-15 Pad
Location ID: 324766



Photo 1. Photo taken from the entrance of Location, illustrating Operator's sign, which needs to be corrected due to an inaccurate Well API #.



Photo 2. Photo taken the wellhead of the Location, illustrating the Operator's sign, which needs to be corrected due to an inaccurate Well API #.

Inspection Photos
Location Name: Fuqua 18-15 Pad
Location ID: 324766



Photo 3. Photo taken from the eastern edge of pad, facing east. Photo illustrates the Operator bulldozed the disturbance feature in response to a 2012 E&P waste release for a proposed controlled burn. The disturbance feature has reclaimed back to reference area conditions.



Photo 4. Photo taken from the southeastern working pad, facing North. Photo illustrates broken fence.

Inspection Photos
Location Name: Fuqua 18-15 Pad
Location ID: 324766



Photo 5. Photo taken from the northern interim reclamation area, facing southwest. Photo illustrates the area consists mostly of annual vegetation, which is not reflective of reference area conditions.



Photo 6. Photo taken near the tank battery. Photo illustrates weeds, including Canada Thistle and Russian thistle. Comply with Rules 606.c. and 1003.f.

Inspection Photos

Location Name: Fuqua 18-15 Pad

Location ID: 324766



Photo 7. Photo taken from the western interim reclamation area, facing northwest. Photo illustrates the area consists mostly of annual vegetation, which is not reflective of reference area conditions.



Photo 8. Photo taken from the entrance of the Location, facing south. Photo illustrates the annual vegetation.

Inspection Photos
Location Name: Fuqua 18-15 Pad
Location ID: 324766



Photo 9. Photo taken from the southeast working pad at tank battery secondary containment. Photo illustrates that the liner is inadequate. Comply with Rule 603.o.



Photo 10. Photo taken from the tank battery. Photo illustrates missing caps/covers on equipment. Operator shall implement wildlife BMPs. Operator shall also manage weeds. Comply with Rule 902.b. and 606.

Inspection Photos
Location Name: Fuqua 18-15 Pad
Location ID: 324766



Photo 11. Photo taken at the tank battery. Photo illustrates evidence of a nest (near another nest, see Photo 12). This appears to be an owl's nest based on the surrounding evidence.




Photo 12. Photo taken at the tank battery. Photo illustrates evidence of a second nest found within a few feet of the first one.