

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/08/2024

Submitted Date:

10/08/2024

Document Number:

699506448

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
450063 _____ MEDINA, JUSTIN _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256212	WELL	PR	04/01/2024	OW	005-07485	Sunset 4-65 21-22 4BH	PR
256213	WELL	PR	04/01/2024	OW	005-07486	Sunset 4-65 21-22 3AH	PR
256290	WELL	PR	04/16/2023	OW	005-07487	Grande 4-65 20-19 3CH	PR
256291	WELL	PR	04/16/2023	OW	005-07488	Grande 4-65 20-19 4AH	PR
256292	WELL	PR	04/16/2023	OW	005-07489	Grande 4-65 20-19 4CH	PR
256293	WELL	PR	04/01/2024	OW	005-07490	Sunset 4-65 21-22 3BH	PR
450062	WELL	SI	12/01/2023	OW	005-07271	Grande 4-65 20-19 3AH	SI

General Comment:

There have been no changes to equipment on location since previous inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 256212 Type: WELL API Number: 005-07485 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256213 Type: WELL API Number: 005-07486 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256290 Type: WELL API Number: 005-07487 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256291 Type: WELL API Number: 005-07488 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256292 Type: WELL API Number: 005-07489 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256293 Type: WELL API Number: 005-07490 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450062 Type: WELL API Number: 005-07271 Status: SI Insp. Status: SI

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/04/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, clear.	medinaj	10/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506449	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743746