

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2024

Submitted Date:

10/11/2024

Document Number:

699506456

FIELD INSPECTION FORM

Loc ID: 484179 Inspector Name: MEDINA, JUSTIN On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 10243
Name of Operator: GMT EXPLORATION COMPANY LLC
Address: 4949 S NIAGARA ST SUITE 250
City: DENVER State: CO Zip: 80237

Contact Information:

Contact Name	Phone	Email	Comment
Eberhardt, Whitney	303-586-9289	w.eberhardt@gmtexploration.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484722	WELL	SI	08/01/2024	OW	039-06754	Red Lady 6-64 4-6 1HN	PR
484723	WELL	DG	07/15/2024		039-06755	Red Lady 6-64 4-6 2HN	PR
484724	WELL	DG	07/16/2024		039-06756	Red Lady 6-64 4-6 3HN	PR
484725	WELL	DG	07/17/2024		039-06757	Red Lady 6-64 4-6 4HN	PR

General Comment:

Flowback inspection

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 484722 Type: WELL API Number: 039-06754 Status: SI Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484723 Type: WELL API Number: 039-06755 Status: DG Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484724 Type: WELL API Number: 039-06756 Status: DG Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484725 Type: WELL API Number: 039-06757 Status: DG Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____
 Comment: _____
 Corrective Action: _____ Date: _____

Workover

Comment: At time of inspection wireline operations and flowback operations were in process. Wells have recently been stimulated.
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, clear.</u>	medinaj	10/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506457	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743750