

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2024

Submitted Date:

10/11/2024

Document Number:

699506458

**FIELD INSPECTION FORM**Loc ID 478811 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 4949 S NIAGARA ST SUITE 250

City: DENVER State: CO Zip: 80237

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Eberhardt, Whitney	303-586-9289	w.eberhardt@gmtexploration.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478801	WELL	PR	08/01/2023	OW	039-06683	Vulcan 6-64 10-8 6HN	PR
478803	WELL	PR	08/01/2023	OW	039-06685	Vulcan 6-64 10-8 3HN	PR
478804	WELL	PR	06/01/2023	OW	039-06686	Vulcan 6-64 10-8 1HN	PR
478806	WELL	PR	08/01/2023	OW	039-06688	Vulcan 6-64 10-8 10HN	PR
478808	WELL	PR	08/01/2023	OW	039-06690	Vulcan 6-64 10-8 8HN	PR

**General Comment:**

Workover inspection

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities				
Facility ID:	478801	Type:	WELL	API Number: 039-06683      Status: PR      Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	478803	Type:	WELL	API Number: 039-06685      Status: PR      Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	478804	Type:	WELL	API Number: 039-06686      Status: PR      Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	478806	Type:	WELL	API Number: 039-06688      Status: PR      Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	478808	Type:	WELL	API Number: 039-06690      Status: PR      Insp. Status: PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Workover				
Comment:	At tie of inspection rig crew was in process of spotting in equipment and rigging up equipment. Company representative informed me that operations were to pull tubing string and drift, and run Gas lift artificial lift equipment.			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
ECMC Comments				
Comment	User	Date		
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, clear.	medinaj	10/11/2024		
Attached Documents				
You can go to ECMC Images ( <a href="https://ecmc.state.co.us/weblink/">https://ecmc.state.co.us/weblink/</a> ) and search by document number:				
Document Num	Description	URL		
699506459	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743751">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743751</a>		