

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2024

Submitted Date:

10/12/2024

Document Number:

708904790

FIELD INSPECTION FORMLoc ID 335614 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

33 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286397	WELL	PR	06/01/2020	GW	045-12673	CLOUGH RWF 522-11	PR
286398	WELL	PR	06/01/2020	GW	045-12672	CLOUGH RWF 322-11	PR
286399	WELL	PR	06/01/2020	GW	045-12671	CLOUGH RWF 12-11	PR
286400	WELL	PR	08/28/2006	GW	045-12670	CLOUGH RWF 312-11	PR
286401	WELL	PR	08/28/2006	GW	045-12669	CLOUGH RWF 412-11	PR
286402	WELL	PR	08/18/2008	GW	045-12668	CLOUGH RWF 512-11	PR
286403	WELL	PR	01/01/2024	GW	045-12667	CLOUGH RWF 422-11	PR
291839	WELL	PR	01/01/2024	GW	045-12665	CLOUGH RWF 22-11	PR

General Comment:

CECMC Inspection Report Summary

On 10/10/2024 at approximately 12:07 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-11 Pad.

Location # 335614 in Garfield County Colorado.

Location is within High Priority/Density Habitat areas & in close proximity to Black Bear Habitat area.

Location is approximately 268 yards from a creek/drainage that contributes to the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Production tank lacks required labeling with a CA date of 11/11/2024
2. Housekeeping - Open ended piping/available for entry by wildlife/wildlife hazard with a CA date of 10/19/2024
3. Equipment - Burner exhaust stacks on separator units lack bird protection/wildlife hazard with a CA date of 10/19/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Production tank lacks required labeling		
Corrective Action:	Comply with CECMC tank labeling rules	Date:	11/11/2024
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Open ended piping/available for entry by wildlife/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules		Date: 10/19/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	2 unmarked deadman - please refer to photo log All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:	Burner exhaust stacks on separator units lack bird protection/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules	Date:	10/19/2024
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,

Comment:		Tank equipped with telemetry					
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate						
Comment:		Centralized containment					
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
OTHER	1	200 BBLs	STEEL AST		,		
Comment:		Tank equipped with telemetry					
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)	Tank is not labeled/contents unknown						
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate						
Comment:		Centralized containment					
Corrective Action:						Date:	

Venting:

Yes/No	NO					
Comment:						
Corrective Action:					Date:	

Flaring:

Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID:	286397	Type:	WELL	API Number: 045-12673 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286398	Type:	WELL	API Number: 045-12672 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286399	Type:	WELL	API Number: 045-12671 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286400	Type:	WELL	API Number: 045-12670 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286401	Type:	WELL	API Number: 045-12669 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286402	Type:	WELL	API Number: 045-12668 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286403	Type:	WELL	API Number: 045-12667 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	291839	Type:	WELL	API Number: 045-12665 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
		Compaction				
Slope Roughening						
Compaction						Small amount of light compaction
		Culverts				
		Other				Hay bales
		Gravel				Sparse to none in sections
Gravel						Sparse to none in areas
Ditches						
Waddles						
		Sediment Traps				
Hydro Mulch						
		Rip Rap				

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker, Housekeeping & Equipment for corrective actions.	smelserw	10/12/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904791	Inspection 708904790 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743934
708904792	Inspection 708904790 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743935