

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Location Overview: Location is within High Priority/Density Habitat areas & in close proximity to Black Bear Habitat area. Multiple drainages from location contribute to the Colorado River.**

**Section/Township/Range: 11 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4932 Erosion & transport of sediment on cut slope**



**Photo # 4933 Erosion & transport of sediment on cut slope**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4934 Erosion & transport of sediment on cut slope & insufficient BMP's/runoff controls**



**Photo # 4935 Erosion & transport of sediment on cut slope & insufficient BMP's/runoff controls**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4936 Erosion & transport of sediment on cut slope & insufficient BMP's/runoff controls**



**Photo # 4937 Insufficient BMP's/runoff controls**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4938 Insufficient BMP's/runoff controls**



**Photo # 4939 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4940 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**



**Photo # 4941 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4942 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**



**Photo # 4943 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4944 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**



**Photo # 4945 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 32-10 Pad**  
**Location ID: 335659**



**Photo # 4946 Failure to minimize erosion & transport of sediment off location - sediment laden stormwater is traveling through ditch & migrating off location into a vegetated area - insufficient BMP's/runoff controls.**



**Photo # 4947 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill**