

# Final Reclamation and Stormwater Inspection

Date: 10/10/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 407867

Inspection Document #: 708201686

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 1.** Photo taken from the southeastern/eastern portion of the disturbance area. Photo illustrates that the eastern side of the disturbance area appears to be progressing towards reclamation standards with evidence of vegetation establishment.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 2.** Photo taken from the eastern side of the disturbance area. Red polygon illustrates approximate extent of erosion degradation (e.g. riling) and sediment deposition in the reclaimed portions. Additional stormwater control measures and/or maintenance required to stabilize the soil and prevent sediment laden stormwater from exiting off location.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 3.** Continued from Photo 2; erosion degradation (e.g. riling) observed.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 4.** Additional stormwater erosion degradation (e.g. riling) observed on the southern portion of the disturbance area.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 5.** Northwestern disturbance area. Reclaimed portions don't appear to be progressing towards Rule 1004 standards and regulations. Additional reclamation activities are required.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 6.** Northern disturbance area. Reclaimed portions don't appear to be progressing towards Rule 1004 standards and regulations. Additional reclamation activities are required.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 7.** Western disturbance area. Reclaimed portions don't appear to be progressing towards Rule 1004 standards and regulations. Additional reclamation activities are required.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 8.** Southern/southwestern disturbance area. The outlined red polygon illustrates a portion of the disturbance area that does not appear to have been reclaimed; no evidence of drill rows and/or hydromulch observed.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 9.** Southern/southwestern disturbance area. The outlined red polygon illustrates a portion of the disturbance area that does not appear to have been reclaimed; no evidence of drill rows and/or hydromulch observed.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 10.** Southern/southwestern disturbance area. The outlined red polygon illustrates a portion of the disturbance area that does not appear to have been reclaimed; no evidence of drill rows and/or hydromulch observed.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 11.** Google Earth aerial imagery (circa 04/2023) illustrating that equipment appears to have been staged on the southern/southwestern portion of the disturbance area (in reference to Photos 7-10); these areas could potentially be compacted and/or were not reclaimed.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 12.** Northwestern disturbance areas; facing east. Reclaimed portions don't appear to be progressing towards Rule 1004 standards and regulations. Additional reclamation activities are required.

Inspection Photos  
Location Name: Jeffers #1  
Location ID: 407867



**Photo 13.** Northeastern disturbance areas; facing south. Photo illustrates the difference between the northern (right of dotted line) and eastern (left of dotted line) reclaimed portions. The northern areas do not appear to be progressing towards reclamation standards and regulations. Additional reclamation activities are required.