

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2024

Submitted Date:

10/08/2024

Document Number:

710500399

FIELD INSPECTION FORMLoc ID 308196 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264043	WELL	PR	02/01/2013	CBM	071-07654	SHOVELHEAD 13-35	EI
265399	PIT	AC			-	SHOVELHEAD 13-35 ONSITE	EI

General Comment:

This is an Environmental Inspection for the Shovelhead 13-35, Location ID 308196, located in Las Animas County, Colorado. Pit Facility ID 265399 has an open Form 15 Doc # 403762276.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:		<div>Well placard on meter house. WDID stickers are illegible</div> <div>Update stickers per Rule 605.g.</div>			
Corrective Action:				Date:	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Other		# 1		corrective date	
Comment:		Insulation in sound panels is dilapidated			
Corrective Action:		Comply with Rule 606		Date: 11/08/2024	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	264043	Type:	WELL	API Number:	071-07654	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	265399	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water	Lined: NO	Pit ID:	Lat:	Long:
----------------------	-----------	---------	------	-------

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment: Form 15 filed to update Pit Coordinates

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

Attached Documents

You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
403950204	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738240
710500400	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738231