

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6SE1W

Location ID: 334965

Date: 10/14/2024



Oct 14, 2024 at 10:56:08  
Parachute CO 81635  
United States



Oct 14, 2024 at 10:57:17  
Parachute CO 81635  
United States

Location Entrance – Photo #04159

Wellheads – Photo #04160

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6SE1W

Location ID: 334965

Date: 10/14/2024



Separators – Photo #04162



Tank Battery – Photo #04163

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6SE1W

Location ID: 334965

Date: 10/14/2024



**Insufficient Erosion Control – Photo #04165**



**Insufficient Erosion Control/Transport of Sediment From  
Lease Road – Photo #04166**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6SE1W

Location ID: 334965

Date: 10/14/2024



Transport of Sediment From Lease Road – Photo #04167



Transport of Sediment From Lease Road – Photo #04168