

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/08/2024

Submitted Date:

10/09/2024

Document Number:

693807773**FIELD INSPECTION FORM**Loc ID 323804 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS STREET SUITE 5050City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                       | Comment         |
|------------------|--------------|-----------------------------|-----------------|
| Browning, Chuck  | 970-433-4139 | chuck.browning@state.co.us  | Field Inspector |
| Gross, Jason     |              | jgross@blm.gov              |                 |
| Labowskie, Steve |              | steve.labowskie@state.co.us |                 |
| Lapham, Ken      | 979-877-4951 | klapham@locin.energy        | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 210841      | WELL | PR     | 12/01/2023  | GW         | 045-06599 | FEDERAL 27-16 | PR          |

**General Comment:**

ECMC staff performed a routine field inspection on 10/8/2024.  
 Issues were found requiring corrective action. See inspection text and photos for details.  
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action  |        | Date: |  |
| Type               | Main   |       |  |
| comment:           |        |       |  |
| Corrective Action  |        | Date: |  |

Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 970-858-7546

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                  |       |  |
|--------------------|------------------|-------|--|
| <b>Fencing/:</b>   |                  |       |  |
| Type               | WELLHEAD         |       |  |
| Comment:           | Hogwire & T-post |       |  |
| Corrective Action: |                  | Date: |  |
| Type               | TANK BATTERY     |       |  |
| Comment:           | Hogwire & T-post |       |  |
| Corrective Action: |                  | Date: |  |

|                     |  |       |                 |
|---------------------|--|-------|-----------------|
| <b>Equipment:</b>   |  |       | corrective date |
| Type: Bradenhead    | # 1  |       |                 |
| Comment:            |  |       |                 |
| Corrective Action:  |  | Date: |                 |
| Type: Gas Meter Run | # 1  |       |                 |
| Comment:            | Located .25 miles NW at intersection of access road and FS Rd 201.<br>Calibrated 5/28/2024 |       |                 |
| Corrective Action:  |  | Date: |                 |

|                                   |   |  |                  |
|-----------------------------------|---|--|------------------|
| Type: Compressor                  | # 1   |  |                  |
| Comment:                          |   |  |                  |
| Corrective Action:                |   |  | Date:            |
| Type: Dehydrator                  | # 1   |  |                  |
| Comment:                          |   |  |                  |
| Corrective Action:                |   |  | Date:            |
| Type: Horizontal Heated Separator | # 1   |  |                  |
| Comment:                          |   |  |                  |
| Corrective Action:                |   |  | Date:            |
| Type: Deadman # & Marked          | # 2   |  |                  |
| Comment:                          | Guy line anchors not marked                     |  |                  |
| Corrective Action:                | Install proper guy line markers per Rule 1003.a |  | Date: 10/25/2024 |
| Type: Bird Protectors             | # 1   |  |                  |
| Comment:                          |   |  |                  |
| Corrective Action:                |   |  | Date:            |

**Tanks and Berms:**

|                    |   |           |             |         |                       |       |
|--------------------|---|-----------|-------------|---------|-----------------------|-------|
| Contents           | # | Capacity  | Type        | Tank ID | SE GPS                |       |
| PRODUCED WATER     | 1 | <100 BBLS | PBV PLASTIC |         | 39.419979,-108.969239 |       |
| Comment:           |   |           |             |         |                       |       |
| Corrective Action: |   |           |             |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    |       |
|                    |    | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  |       |
|                    |  | Date: |

| Inspected Facilities    |                            |       |                        |             |           |         |    |               |    |
|-------------------------|----------------------------|-------|------------------------|-------------|-----------|---------|----|---------------|----|
| Facility ID:            | 210841                     | Type: | WELL                   | API Number: | 045-06599 | Status: | PR | Insp. Status: | PR |
| Producing Well          |                            |       |                        |             |           |         |    |               |    |
| Comment:                | Flowing                    |       |                        |             |           |         |    |               |    |
| Corrective Action:      |                            |       |                        | Date:       |           |         |    |               |    |
| BradenHead              |                            |       |                        |             |           |         |    |               |    |
| Date of Last Brhd Test: | 03/05/2024                 |       | Annual Brhd Completed? | Yes         |           |         |    |               |    |
| Last Brhd Test Results  | Initial Surf Csg Pressure: | 0     | Fluid Type:            | NONE        |           |         |    |               |    |
|                         | End Surf Csg Pressure:     | 0     |                        |             |           |         |    |               |    |
| Comment:                |                            |       |                        |             |           |         |    |               |    |
| Corrective Action:      |                            |       |                        | Date:       |           |         |    |               |    |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 403951219    | INSPECTION SUBMITTED        | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739428">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739428</a> |
| 693807784    | Inspection photos 10/8/2024 | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739426">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739426</a> |