

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/08/2024

Submitted Date:

10/09/2024

Document Number:

708302882**FIELD INSPECTION FORM**

|  |                                    |   |                   |   |
|--|------------------------------------|---|-------------------|---|
| Loc ID<br>335692   | Inspector Name:<br>Morris, Matthew | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>10 Number of Comments<br>2 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested |
| <b>Operator Information:</b><br>ECMC Operator Number: <u>10456</u><br>Name of Operator: <u>CAERUS PICEANCE LLC</u><br>Address: <u>1001 17TH STREET #1600</u><br>City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |                                    |   |                   | <b>ANY CORRECTIVE ACTION(S) FROM<br/>PREVIOUS INSPECTIONS THAT HAVE NOT<br/>BEEN ADDRESSED ARE STILL APPLICABLE</b>   |

| <b>Contact Information:</b> |       |                                |         |
|-----------------------------|-------|--------------------------------|---------|
| Contact Name                | Phone | Email                          | Comment |
| , CAERUS                    |       | ecmc.inspections@qb-energy.com |         |

| <b>Inspected Facilities:</b> |      |        |             |            |           |                              |             |
|------------------------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| Facility ID                  | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
| 352                          | WELL | PR     | 05/18/2009  | GW         | 045-15493 | N.PARACHUTE EF07D-20 C29 59  | PR          |
| 353                          | WELL | PR     | 01/17/2011  | GW         | 045-15490 | N.PARACHUTE EF07B-20 C29 59  | PR          |
| 354                          | WELL | PR     | 02/01/2014  | GW         | 045-15491 | N.PARACHUTE EF07C-20 C29 59  | PR          |
| 355                          | WELL | PR     | 01/25/2010  | GW         | 045-15492 | N. PARACHUTE EFH320-10N C29  | PR          |
| 367                          | WELL | PR     | 01/20/2010  | GW         | 045-15488 | N. PARACHUTE EFH320-8N C29   | PR          |
| 294653                       | WELL | PR     | 08/01/2019  | GW         | 045-15552 | N. PARACHUTE EF12B-20 C29 59 | PR          |
| 294658                       | WELL | PR     | 01/18/2011  | GW         | 045-15557 | N. PARACHUTE EF05D-20 C29 59 | PR          |
| 295207                       | WELL | PR     | 02/11/2011  | GW         | 045-15708 | N.PARACHUTE EF10B-20 C29 59  | PR          |

**General Comment:**

[CECMC Inspection Report Summary](#)

On 10/8/2024 at approximately 13:45, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, N.PARACHUTE-65S95W/29NENW at Location ID #335692 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- Undesirable plant species/weeds across location
- Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Undesirable plant species/weeds present across location. |       |            |
| Corrective Action: | Remove undesirable plant species/weeds from location.    | Date: | 10/16/2024 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | WELLHEAD  |       |  |
| Comment:           | Concrete barriers                                   |       |  |
| Corrective Action: |   | Date: |  |
| Type               | OTHER   |       |  |
| Comment:           | Gas meters/gas lift protected by concrete barriers. |       |  |
| Corrective Action: |   | Date: |  |

**Equipment:**

|                           |                      |       |                 |
|---------------------------|----------------------|-------|-----------------|
|                           |                      |       | corrective date |
| Type: Gas Meter Run       | # 8                  |       |                 |
| Comment:                  |                      |       |                 |
| Corrective Action:        |                      | Date: |                 |
| Type: Ancillary equipment | # 1                  |       |                 |
| Comment:                  | CataDyne line heater |       |                 |
| Corrective Action:        |                      | Date: |                 |
| Type: Bradenhead          | # 8                  |       |                 |
| Comment:                  |                      |       |                 |
| Corrective Action:        |                      | Date: |                 |



| Inspected Facilities   |        |       |      |   |
|--|--------|-------|------|---|
| Facility ID:   | 352    | Type: | WELL | API Number: 045-15493 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 353    | Type: | WELL | API Number: 045-15490 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 354    | Type: | WELL | API Number: 045-15491 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 355    | Type: | WELL | API Number: 045-15492 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 367    | Type: | WELL | API Number: 045-15488 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 294653 | Type: | WELL | API Number: 045-15552 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 294658 | Type: | WELL | API Number: 045-15557 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 295207 | Type: | WELL | API Number: 045-15708 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |

| Producing Well     |  |  |                   |
|--------------------|--|--|-------------------|
| Comment:           |  |  |                   |
| Corrective Action: |  |  | Date: <div></div> |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                    |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|----------------------------|
|                  |                 |                         |                       | Material Handling And Spill Prevention |                          |                            |
|                  |                 | Compaction              |                       |  |                          |                            |
| Compaction       |                 |                         |                       |  |                          |                            |
| Gravel           |                 |                         |                       |  |                          |                            |
| Other            | Fail            |                         |                       |  |                          | Unprotected soil stockpile |
|                  |                 | Gravel                  |                       |  |                          |                            |
| Ditches          |                 |                         |                       |  |                          |                            |
|                  |                 | Culverts                |                       |  |                          |                            |
|                  |                 | Ditches                 |                       |  |                          |                            |

Comment: [Protect or remove soil stockpile.](#)[Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.](#)Corrective Action: **1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.**Date: 10/24/2024Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403951996    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740063">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740063</a> |
| 708302883    | Photo Log            | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740045">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740045</a> |