

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/08/2024

Submitted Date:

10/09/2024

Document Number:

708302884**FIELD INSPECTION FORM**Loc ID 335641 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286474	WELL	PR	11/15/2012	GW	045-12678	N PARACHUTE WF04A-31A36A596	PR
286475	WELL	SI	05/01/2024	GW	045-12677	N PARACHUTE WF01B-36A36A596	SI
286476	WELL	PR	11/15/2012	GW	045-12682	N PARACHUTE WF01D-36A36A596	PR
286477	WELL	PR	11/15/2012	GW	045-12683	N PARACHUTE WF04D-31A36A596	PR
286478	WELL	PR	08/01/2019	GW	045-12684	N PARACHUTE WF04B-31A36A596	PR
289754	WELL	PR	11/15/2012	GW	045-13879	N PARACHUTE WF04C-31A36A596	PR
289819	WELL	SI	05/01/2024	GW	045-13884	N PARACHUTE WF04E-31A36A596	SI

General Comment:**CECMC Inspection Report Summary**

On 10/8/2024 at approximately 14:05, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, N PARACHUTE/WF01B-36A36A596 at Location ID #335641 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Unsecured storage house poses a wildlife entry hazard

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Unsecured storage house poses wildlife entry hazard.		
Corrective Action:	Secure equipment to comply with Rule 608.e.	Date:	10/14/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meters/lift protected by concrete barriers.		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Concrete barriers		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 286474 Type: WELL API Number: 045-12678 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286475 Type: WELL API Number: 045-12677 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: Last produced April 2024 per production report.Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286476 Type: WELL API Number: 045-12682 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286477 Type: WELL API Number: 045-12683 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286478 Type: WELL API Number: 045-12684 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289754 Type: WELL API Number: 045-13879 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289819 Type: WELL API Number: 045-13884 Status: SI Insp. Status: SI

Idle Well		
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<div>Last produced April 2024 per production report.</div>	
Corrective Action:	<div></div>	Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				
		Compaction				
Gravel						
Compaction						
		Ditches				
		Culverts				
				Material Handling And Spill Prevention		

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403951997	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740064
708302885	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740046