

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2024

Submitted Date:

10/09/2024

Document Number:

708904765**FIELD INSPECTION FORM**Loc ID 324343 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280585	WELL	PR	07/01/2021	GW	045-11294	HMU 6-11 (J6SE)	PR

**General Comment:****CECMC Inspection Report Summary**

On 10/09/2024 at approximately 14:49 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at QB Energy HMU 6-11 (J6SE) Pad.

Location # 324343 in Garfield County Colorado.

Please refer to inspection 708904507 conducted on 09/06/2024, previous corrective action has not been completed.

Location is within High Priority/NSO/Black Bear Habitat areas.

Location is approximately 140 yards from East Mamm Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Wellhead lacks required signage/does not comply with CECMC rules with a CA date of 10/07/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Split pad/Remote location - Wellhead only, tank battery &amp; separator located on the HMU 6-15A (J6SEB) location # 432265

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead lacks required signage/does not comply with CECMC rules		
Corrective Action:	Comply with CECMC wellhead signage rules	Date:	10/07/2024

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Jersey barriers around wellhead		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Pressure transducer located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	280585	Type:	WELL	API Number:	045-11294	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction in some sections
Berms						
		Ditches				
Culverts						
		Other				Mag chloride on some sections of lease road
Gravel						Sparse to none in some areas
Compaction						Light compaction in some areas
		Culverts				
Rip Rap						
Ditches						
Check Dams						
		Gravel				Sparse to none in sections
Retention Ponds						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Signs/Marker for corrective action	smelserw	10/09/2024
Split pad/Remote location - Wellhead only, tank battery & separator located on the HMU 6-15A (J6SEB) location # 432265		

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403952022	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740138">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740138</a>
708904766	Inspection 708904765 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740136">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740136</a>
708904767	Inspection 708904765 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740137">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740137</a>