

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2024

Submitted Date:

10/09/2024

Document Number:

709100423

FIELD INSPECTION FORMLoc ID 312228 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Alex Fischer		alex.fischer@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Dylan Edwardson		dylan.edwardson@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Ryan Finley		rfinley@entradainc.com	
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219731	WELL	PR	11/01/2018	OW	075-06955	PROPST C-1X	EI

General Comment:

On September 30, 2024, ECMC Environmental Staff Krystal Heibel and Dylan Edwardson conducted an environmental field inspection of Western Operating Company (Western) Probst C-1X (Location ID: 312228).

Weather was sunny and temperature was about 80 degrees Fahrenheit.

For the most recent field inspection report of this facility, please refer to Document #708200709

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:		Emergency Contact number visible from a distance		Date: _____
Corrective Action:				
Good Housekeeping:				
Type				
Comment:	Wildlife protections (netting) observed around secondary containment of day tank			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	Pump Jack	<= 1 bbl		
Comment:	Hydrocarbon staining observed within metal shed, around pump jack, and around wellhead.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 11/06/2024
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	219731	Type:	WELL	API Number:	075-06955	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Refer to FIR, Doc# 708201669 for additional Interim Reclamation and Stormwater Inspection information.				
Corrective Action:						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403950609	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738940
709100427	Pics	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738930