

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2024

Submitted Date:

10/09/2024

Document Number:

696306804

**FIELD INSPECTION FORM**Loc ID 420717 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 20165 NORTH 67TH AVENUE 122A

City: GLENDALE State: AZ Zip: 85308

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Kelly, George	(888) 842-1090	phxresources@aol.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Wolfe, Stephen		stephen.wolfe@state.co.us	
Gilliland, Harrison		phxresources1@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420712	WELL	PR	07/01/2022	OW	123-32689	Cass Farms 11-9H	PR

**General Comment:**

Follow-Up Inspection to FIR 696305332 dated 10.11.2023

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24-Hour Emergency Contact Number not valid; see photos

Corrective Action: Install sign to comply with Rule 605.e.

Date: 11/11/2024

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained Soil at Wellhead and Pumping Unit; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	10/26/2022
Type	WEEDS		
Comment:	Weeds on Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	10/26/2022
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Electrical Panels on West Side of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	10/27/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric Motor		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	500 BBLS	HEATED STEEL AST		40.594160,-104.334260	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Field Flare	
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 420712 Type: WELL API Number: 123-32689 Status: PR Insp. Status: PR

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI - Shut-In at the time of this Inspection.  
No Production has been Repored since 07.01.2022

Corrective Action: Report Production on Form 7 per 413 Rules

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 12/20/2021

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No current Form 17 on File. Last Form 17 on File is from 12.21.2021

Corrective Action: Perform Bradenhead Test and Submit Form 17 per Rule 419.b(4)A

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>On Tuesday 10/01/2024 at approximately 14:43, I, Inspector Erica Petrie, conducted an a Follow-Up Field Inspection at Phoenix Resources LLS, Cass Farms 11-9H, Location #420717 in Weld County, Colorado.</p> <p>While there, I observed Production Operations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds on Entire Location; see photos. Comply with Rule 606. Orinigal Corrective Action Date of 10.26.2022 remains the same</p> <p>Stained Soil at Wellhead and Pumping Unit; see photos. Orinigal Corrective Action Date of 10.26.2022 remains the same</p> <p>Unmarked Riser at Electrical Panels; see photos. Corrective Action Date of 10.27.2023</p> <p>No current Production Reported. Last Production reported on 07.01.2022. Report Production on Form 7 per 413 Rules.</p> <p>No current Form 17 Bradenhead Test on File. Last Form 17 on File 12.22.2021. Perform Bradenhead Test and Submit Form 17 per Rule 419.b(4)A</p> <p>New Corrective Action</p> <p>24-Hour Emergency Contact Number not valid; see photos. Install sign to comply with Rule 605.e. Corrective Action date 11.11.2024</p>	petriee	10/09/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403951757	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739794">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739794</a>
696306805	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739790">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6739790</a>