

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2024

Submitted Date:

10/09/2024

Document Number:

715201030

FIELD INSPECTION FORM

Loc ID 380922 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10634
Name of Operator: P O & G OPERATING LLC
Address: 5847 SAN FELIPE SUITE 3200
City: HOUSTON State: TX Zip: 77057

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wolfe, Stephen		stephen.wolfe@state.co.us	
Nash, Charlotte	(713) 589-8186	charlotte_nash@pogresource.com	
Shalberg, Greg		gregshalberg@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208213	WELL	PR	12/18/2014	LO	017-07148	Harker Ranch 14-1	TA

General Comment:

[SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment](#)

Location

Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Fencing laying on the ground		
Corrective Action:			Date:
Type	STORAGE OF SUPL		
Comment:	Horsehead and counterweights stored next to unit		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around locaton		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Cathodic rectifier and electric panel		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:			Date:
Type: Prime Mover	# 0		
Comment:	Removed from unit		

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 208213 Type: WELL API Number: 017-07148 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is TA at time of inspection. Passing MIT performed on 12/8/17. Well is past due for MIT (due on 12/8/22)

Corrective Action: Contact ECMC Engineering for directives Date: 10/19/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403951995	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740062
715201062	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6740056