

Inspection Photos

10/15/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 479149

Inspection Doc: 696206375

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 1: Photos 1-2 taken from the west end of the working pad surface. Photos provide an overview of the pad from north, northeast, southeast to south. Interim reclamation operators “in process” at time of inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 3: Photos show wells on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



October 15, 2024

Photo 4: Photo taken from the north end of the Location, facing north. Pursuant to Operator's Reclamation plan (#403909113), road will be reclaimed; pursuant to Form 4 #403940442, road will be retained until well completion operations are finished BJU M23A 496 due to a shared completions pad and temporary frac lines are in place



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 5: Photos taken from the northeast corner of the working pad surface. Photo shows a hole on the location; hole is approximately 2-3' x 1', depth is unknown. Hole requires safety fence/BMPs to prevent access by people of wildlife.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 6: Photo example showing soils on the working pad surface are loose/powdery and at risk of becoming fugitive dust.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 7: Photo taken with use of a sUAS during inspection. Photo taken south of the Location, facing north. Photo provides an overview of the Location, and shows interim reclamation activities “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 8: Photos taken with use of a sUAS during inspection. Photos provides an overview of the Location, and shows interim reclamation activities “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 9: Photos taken with use of a sUAS during inspection. Photos taken from the east of the of the location, facing southwest/northwest. Photos provides an overview of the Location, and shows interim reclamation activities “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 10: Photos taken from the interim areas on the northeast end of the Location. Photos show perimeter stormwater and erosion control BMPs are missing or insufficient. BMPs previously implemented, including erosion logs, appear to have have either been removed, not maintained, or covered during current construction/interim reclamation operations.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 11: Photo taken with use of a sUAS during inspection. Photos taken from the northeast end of the of the location, facing northwest. Photos show perimeter stormwater and erosion control BMPs are missing or insufficient. BMPs previously implemented, including erosion logs, appear to have have either been removed, not maintained, or covered during current construction/interim reclamation operations.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 12: See comments under photo 11.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 13: Photo taken with use of a sUAS during inspection. Photos taken from the east end of the of the location, facing south. Photos show perimeter stormwater and erosion control BMPs are missing or insufficient. BMPs previously implemented, including erosion logs (arrow), appear to have have either been removed, not maintained, or covered during current construction/interim reclamation operations.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149



Photo 14: Continued from photo 13; see comments under photo 13.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 479149




Photo 15: Continued from photo 13; see comments under photo 13.