

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6486 From entrance to location



Photo # 6487 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118




Photo # 6488 Location



Photo # 6489 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6490 Location



Photo # 6491 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6492 Location



Photo # 6493 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6494 Location



Photo # 6495 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6496 Location



Photo # 6497 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6498 Location




Photo # 6499 Battery sign weathered & some info starting to fade



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6500 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 6501 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6502 Hole in liner/liner needs maintenance



Photo # 6503 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6504 Hole in liner/liner needs maintenance



Photo # 6505 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 11-32

Location ID: 324118



Photo # 6506 Capacity on tank label fading & becoming illegible

