

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

10/10/2024

Document Number:

699700418

**FIELD INSPECTION FORM**Loc ID 316581 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10384

Name of Operator: GENESIS GAS &amp; OIL COLORADO LLC

Address: 1141 NORTH LOOP 1604 E 105-414

City: SAN ANTONIO State: TX Zip: 78232

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments  
2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roberts, James		j75rober@blm.gov	BLM meeker
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286504	WELL	PR	11/01/2022	CBM	103-10895	FLETCHER GULCH 4-13	EI

**General Comment:**

ECMC Environmental Inspection. All previous unresolved CAs for this location still apply to this inspection.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:			Potentially impacted material adjacent to the wellhead.	
Corrective Action:			Control and contain spills/releases and clean up per Rule 912.a.	Date:
Produced Water	Pump Jack			
Comment:			Potentially impacted material adjacent to the pump jack exhaust.	
Corrective Action:			Control and contain spills/releases and clean up per Rule 912.a.	Date:

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 10/17/2024 Doc [#699700418]

Page 2 of 3

Inspected Facilities

Facility ID: 286504    Type: WELL    API Number: 103-10895    Status: PR    Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403953193	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741114">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741114</a>
699700419	20240924 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741110">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6741110</a>