

# Inspection Photos

ID#479908

Operator: **DOVER ATWOOD CORPORATION**

Inspection Date: 10/14/2024

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos




**Photo 1.** Facing northwest at the facility. The tank does not have secondary containment and the labeling is faded. There are weeds all around the equipment which is a fire hazard.





## Inspection Photos



**Photo 2.** There is netting on the open top tank. Some of the edges are torn and need maintenance.





## Inspection Photos



**Photo 3.** Northeast at the facility. There is a fenced in storage yard adjacent to this facility. Oil and gas equipment is being stored inside the fenced area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

ID:479908 | Date: 10/14/2024