

# Inspection Photos

API# 009-06598

Operator: **DOVER ATWOOD CORPORATION**

Inspection Date: 10/14/2024

County: BACA



## Inspection Photos



**Photo 1.** Facing toward the tank battery approx. 1200' east of the wellsite. There is insufficient secondary containment of the tank.



Inspection Photos



**Photo 2.** There is no netting on the open top tank contains a hardened E&P substance.



## Inspection Photos



**Photo 3.** Facing toward the equipment. There are weeds around the equipment which is a fire hazard.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API# 009-06598 | Date: 10/14/2024

Inspection Photos



**Photo 4.** Facing west at the wellsite.



## Inspection Photos



**Photo 5.** There is buckets of chemical at red arrow that need to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API# 009-06598 | Date: 10/14/2024