

Inspection Photos

October 15th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306796

Inspection Document #: 714001355

La Plata County, CO

Township: SWSW 7 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southern Ute P 2
Location ID: 306796

10/15/24
83° E



Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08782

Inspection Photos
Location Name: Southern Ute P 2
Location ID: 306796



Photo 2. View of eastern and western interim reclamation areas composed of but not limited to Purple Threeawn, Rubber Rabbitbrush and Intermediate Wheatgrass.

Inspection Photos
Location Name: Southern Ute P 2
Location ID: 306796



Photo 3. Stormwater issues observed along the access road. Evidence of sediment transport and deposition. Additional stormwater BMPs along the access road are needed.

Inspection Photos
Location Name: Southern Ute P 2
Location ID: 306796

10/15/24
186° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Intermediate Wheatgrass, Sagebrush and Juniper.

API #: 067-08782