

Inspection Photos

October 15th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306800

Inspection Document #: 714001361

La Plata County, CO

Township: SWNE 13 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southern Ute N2
Location ID: 306800

10/15/24
199° S



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Southern Ute N2
Location ID: 306800

10/15/24
204° SW



Photo 2. View of the western interim reclamation composed predominantly of Intermediate Wheatgrass.

Inspection Photos
Location Name: Southern Ute N2
Location ID: 306800



Photo 3. View of the eastern interim reclamation/cut slope. Area is lacking vegetation with evidence of gully erosion and sediment transport/deposition on the active pad.

Inspection Photos
Location Name: Southern Ute N2
Location ID: 306800



Photo 4. View of produced water tank label that is deteriorating and no longer displaying tank capacity.

Inspection Photos
Location Name: Southern Ute N2
Location ID: 306800

10/15/24
205° SW



Photo 4. Reference area composed of Sagebrush and Smooth Brome.