

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2024

Submitted Date:

10/17/2024

Document Number:

713601532**FIELD INSPECTION FORM**Loc ID 321185 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
Kelly, George	(888) 858-7886	envexbaca@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479908	TANK BATTERY	AC	05/04/2021		-	Mama Bear Tank	RI

**General Comment:**

This is a reclamation inspection of the Mama Bear Tank facility.  
Operator is directed to perform corrective actions immediately.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	There is no sign posted at ths facility.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	11/18/2024

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	There are tall weed debris around the equipment which is a fire hazard.		
Corrective Action:	Comply with Rule 606.	Date:	10/24/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1		Open Top		,	
Comment:						
Corrective Action:						Date: _____

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			
Comment:	The secondary containment is inadequate to contain a spill.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: _____

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date: _____

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601533	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750869">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750869</a>