

Construction and Stormwater Inspection

Date: 10/16/2024

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 449925

Inspection Document #: 708201708

Adams County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 2. Vehicle track out pad at the location entrance requires maintenance.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 3. Sediment is beginning to collect at the location entrance and transferring onto the adjacent roadway. Additional BMPs/maintenance is required.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 4. Sediment trap located near the southern portion of the drilling pad, west of entrance.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 5. Undesirable vegetation was observed on the western (existing) topsoil stockpile.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 6. Ditch and berm has been constructed around the perimeter of the location.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 7. Appears that topsoil has been salvaged from the eastern interim areas as part of a drilling pad expansion. The topsoil stockpile appears to have been equipment tracked for short term stabilization.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 8. Continued from Photo 7; perimeter stormwater BMPs and topsoil stockpile pictured.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 9. Overview of drilling pad expansion on the eastern portion of the location.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 10. Taken from the southeast corner of the location. Photo illustrates perimeter ditch and berm constructed.

Inspection Photos
Location Name: Alma 1S-66-2524 Pad
Location ID: 449925



Photo 11. Sediment trap located near the southern portion of the drilling pad, east of entrance.