

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 10/15/2024



Location Entrance – Photo #04226



Wellheads – Photo #04229



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 10/15/2024



Wellhead/Meter – Photo #04227



Separators – Photo #0



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 10/15/2024



**Tank Battery – Photo #04230**



**Insufficient Erosion Control – Photo #04234**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 10/15/2024



**Insufficient Erosion Control/Sediment Transport from Lease Road – Photo #04236**



**Insufficient Erosion Control/Sediment Transport from Lease Road – Photo #04237**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 10/15/2024



**Insufficient Erosion Control/Sediment Transport from Lease  
Road – Photo #04238**