

Inspection Photos

Location Name: TEP Rocky Mountain LLC Duggan RWF 14-29 Pad

Location ID: 429828




Photo # 6398 From entrance to location

Photo # 6399 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 14-29 Pad

Location ID: 429828



Photo # 6400 Location



Photo # 6401 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 14-29 Pad

Location ID: 429828



Photo # 6402 Location



Photo # 6403 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 14-29 Pad

Location ID: 429828



Photo # 6404 Location



Photo # 6405 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 14-29 Pad

Location ID: 429828



Photo # 6406 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 6407 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Duggan RWF 14-29 Pad

Location ID: 429828



Photo # 6408 Secondary containment liner showing some signs of disrepair



Photo # 6409 Small amount of staining near chemical tank containment