

Final Reclamation and Stormwater Inspection

Date: 10/16/24

Operator: Axis Exploration LLc - 10646

Location ID: 320193

Inspection Document #: 713901105

Adams County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Qualls 5-13
Location ID: 320193



ECMC
2° N
10/16/24, 2:32 PM



ECMC
169° S
10/16/24, 2:31 PM

Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates the tank battery pad still remains.

Photo 2. The photo was taken at the tank battery location facing South. Refer to the comment for photo 1.

Inspection Photos
Location Name: Qualls 5-13
Location ID: 320193



ECMC
330° NW
10/16/24, 2:32 PM

Photo 3. The photo was taken at the tank battery location facing Northwest. The photo illustrates debris on the pad.



ECMC
77° E
10/16/24, 2:32 PM

Photo 4. The photo was taken at the tank battery location facing East. The photo illustrates weeds and poor crop growth along the well access road.

Inspection Photos
Location Name: Qualls 5-13
Location ID: 320193



Photo 5. The photo was taken along access road to the well location facing East. The photo illustrates growth along the access road is not representative of reference crop.



Photo 6. The photo was taken at the well location facing North. The photo illustrates crop vegetation at the well location is not representative of reference crop and is dominated by kochia, cereal rye, field bindweed and bare soil.



Inspection Photos
Location Name: Qualls 5-13
Location ID: 320193



Photo 7. The photo was taken at the well location facing Northeast. Refer to the comment for photo 6.



Photo 8. The photo was taken at the well location facing South. Refer to the comment for photo 6.

Inspection Photos
Location Name: Qualls 5-13
Location ID: 320193



Photo 9. The photo was taken at the well location facing West. Refer to the comment for photo 6.



Photo 10. The reference photo was taken near the well location facing Northeast. The photo illustrates the well location is not representative of reference crop.