

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31SEW

Location ID: 334881

Date: 10/17/2024



Southwest Corner of Location – Photo #04275



Wellheads – Photo #04274

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31SEW

Location ID: 334881

Date: 10/17/2024



Wellheads – Photo #04273



Separators – Photo #04284

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31SEW

Location ID: 334881

Date: 10/17/2024



Tank Battery – Photo #04282



ECD (Not in Use)/Methanol Tank – Photo #04283

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31SEW

Location ID: 334881

Date: 10/17/2024



Insufficient Erosion Control – Photo #04276



Insufficient Erosion Control – Photo #04278

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31SEW

Location ID: 334881

Date: 10/17/2024



Insufficient Erosion Control/Degradation – Photo #04279



Sediment Encroaching Into Production Equipment/Degradation – Photo #04280