

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2024

Submitted Date:

10/19/2024

Document Number:

713400399

**FIELD INSPECTION FORM**Loc ID 336054 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

44 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, CHEVRON		rbucogccinspectionreports@chevron.onmicrosoft.com	
, CHEVRON		andrewolson@chevron.com	
, CHEVRON		stephaniebittner@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276277	WELL	PR	02/16/2006	GW	045-10436	SKINNER RIDGE 598-25-2	PR
296980	WELL	PR	02/01/2011	GW	045-16242	SKR 598-25-CV-20	PR
296981	WELL	PR	10/10/2010	GW	045-16243	SKR 598-25-CV-13	PR
296982	WELL	PR	11/15/2010	GW	045-16244	SKR 598-25-CV-12	PR
296983	WELL	PR	10/21/2010	GW	045-16245	SKR 598-25-CV-10	PR
296984	WELL	PR	09/01/2023	GW	045-16246	SKR-598-25-CV 09	PR
296985	WELL	PR	11/10/2010	GW	045-16247	SKR 598-25-CV-17	PR
296986	WELL	PR	12/08/2010	GW	045-16248	SKR 598-25-CV-15	PR
296987	WELL	PR	11/10/2010	GW	045-16249	SKR 598-25-CV-16	PR
296988	WELL	PR	11/18/2010	GW	045-16250	SKR 598-25-CV-14	PR
296989	WELL	PR	01/11/2011	GW	045-16251	SKR 598-25-CV-22	PR
296990	WELL	PR	06/01/2019	GW	045-16252	SKR 598-25-CV-21	PR
296991	WELL	PR	11/10/2010	GW	045-16253	SKR 598-25-CV-18	PR
296992	WELL	PR	10/02/2010	GW	045-16254	SKR 598-25-CV-03	PR
296993	WELL	PR	12/20/2010	GW	045-16255	SKR 598-25-CV-01	PR
296994	WELL	PR	11/10/2010	GW	045-16256	SKR 598-25-CV-19	PR
296995	WELL	PR	05/01/2024	GW	045-16257	SKR 598-25-CV-02	PR
296996	WELL	PR	10/15/2010	GW	045-16258	SKR 598-25-CV-06	PR

296997	WELL	PR	10/09/2010	GW	045-16259	SKR 598-25-CV-11	PR
296998	WELL	PR	06/01/2024	GW	045-16260	SKINNER RIDGE 598-25-CV 08	PR
296999	WELL	PR	05/22/2012	GW	045-16261	SKR 598-25-CV-07	PR
297000	WELL	PR	10/08/2010	GW	045-16262	SKR 598-25-CV-05	PR
297001	WELL	PR	09/18/2010	GW	045-16263	SKR 598-25-CV-04	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 10/16/2024 at approximately 10:47 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection at CHEVRON USA INC SKINNER RIDGE-65S98W/25SESW at Location ID #336054 in Garfield County, Colorado.

Please refer to inspection 713400269 conducted on 08/21/2024, previous corrective action has been completed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

[CECMC Inspection Report Summary](#)

Normal production operations were observed.

**Location****Lease Road:**

Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical labeling on tanks on separators		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	1-877-257-6007/911	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 20		corrective date
Comment:	Bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment: <a href="#">Charge pump</a>		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: <a href="#">Glycol pump</a>		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 20	
Comment:		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: <a href="#">Air compressors</a>		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: <a href="#">Methanol tanks</a>		Date:
Corrective Action:		Date:
Type: Other	# 1	
Comment: <a href="#">Power control building</a>		Date:
Corrective Action:		Date:
Type: Bird Protectors	# 13	
Comment:		Date:
Corrective Action:		Date:
Type: Bradenhead	# 3	
Comment: <a href="#">Bradenhead valve is accessible</a>		Date:
Corrective Action:		Date:
Type: Other	# 4	
Comment: <a href="#">Fire extinguishers</a>		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 20	
Comment:		Date:
Corrective Action:		Date:
Type: Other	# 1	
Comment: <a href="#">Glycol heater</a>		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 20	
Comment:		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 3	
Comment:		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 3	
Comment:		Date:

Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 4				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	Chemical tanks				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:	Telemetry on tank					
Corrective Action:					Date:	

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient			
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	2	OTHER	OTHER		,	
Comment:	Mounted on skids					
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)	350 gal				
Other (Type)	Stainless steel				

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	276277	Type:	WELL	API Number: 045-10436	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296980	Type:	WELL	API Number: 045-16242	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296981	Type:	WELL	API Number: 045-16243	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296982	Type:	WELL	API Number: 045-16244	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296983	Type:	WELL	API Number: 045-16245	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296984	Type:	WELL	API Number: 045-16246	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296985	Type:	WELL	API Number: 045-16247	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	296986	Type:	WELL	API Number: 045-16248	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well					
Corrective Action:					Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296987	Type:	WELL	API Number: 045-16249 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296988	Type:	WELL	API Number: 045-16250 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296989	Type:	WELL	API Number: 045-16251 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296990	Type:	WELL	API Number: 045-16252 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296991	Type:	WELL	API Number: 045-16253 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296992	Type:	WELL	API Number: 045-16254 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296993	Type:	WELL	API Number: 045-16255 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			



Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	296994	Type:	WELL	API Number:	045-16256	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>								
Comment:	Producing well							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	296995	Type:	WELL	API Number:	045-16257	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>								
Comment:	Producing well							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	296996	Type:	WELL	API Number:	045-16258	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>								
Comment:	Producing well							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	296997	Type:	WELL	API Number:	045-16259	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>								
Comment:	Producing well							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	296998	Type:	WELL	API Number:	045-16260	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>								
Comment:	Producing well							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	296999	Type:	WELL	API Number:	045-16261	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>								
Comment:	Producing well							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	297000	Type:	WELL	API Number:	045-16262	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>								
Comment:	Producing well							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	297001	Type:	WELL	API Number:	045-16263	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Ditches				
Compaction						
				Material Handling And Spill Prevention		Chemical tank containments
		Compaction				
		Culverts				
Gravel						Sparse to none in some areas
Berms						
		Berms				
		Gravel				Sparse to none in sections

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400400	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6753292">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6753292</a>