

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



Photo # 5897 From entrance to location



Photo # 5898 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



Photo # 5899 Location



Photo # 5900 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



Photo # 5901 Location



Photo # 5902 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



Photo # 5905 Location



Photo # 5906 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



Photo # 5907 Location



Photo # 5908 Battery lacks required signage

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad  
Location ID: 335744




## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



**Photo # 5911 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 5912 PRV vent line does not comply with CECMC pressure safety device rules**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



**Photo # 5913 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 5914 PRV vent line does not comply with CECMC pressure safety device rules**


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



**Photo # 5915 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 5916 PRV vent line does not comply with CECMC pressure safety device rules**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Pad

Location ID: 335744



**Photo # 5917 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 5918 PRV vent line does not comply with CECMC pressure safety device rules**