

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2024

Submitted Date:

10/14/2024

Document Number:

698602480

**FIELD INSPECTION FORM**Loc ID 303351 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252953	WELL	PR	08/30/1994	GW	125-06830	BROPHY, T 32-12	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Well sign posted at CR and Access Road intersection.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign at wellhead location.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Well sign posted at Gas Meter Run.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Emergency contact information posted on well sign.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Removed Pump Jack drive belt guard noted inside wellhead fencing.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	Less than 1 bbl. Wellhead leaking at packing.			
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).			Date: 10/04/2024

In Containment: No

Comment: Leak at is less than 1 bbl. Notified Field Foremen 10/03/2024. They will shut in for repair.

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		

Comment:	Digital Gas Meter Run. Meter Calibration/Test Log dated 6-13-24. Well Inlet Valve open. Gas Outlet Valve open.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve open. Casing valve open.			
	Active release at wellhead packing. Notified Field Foremen 10/03/2024.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.			
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Electric Motor.			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Bradenhead plumbed to surface.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Shared Gas Meter Shed.			
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	Flowline riser at wellhead with valve and plug.			
Corrective Action:			Date:	

**Venting:**

Yes/No	YES		
Comment:	Fluid leak at wellhead packing. Notified Field Foremen 10/03/2024.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	252953	Type:	WELL	API Number:	125-06830	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  Electronic Well File reflects last Production/Status reported 7/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403956251	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6745233">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6745233</a>
698602491	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6745230">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6745230</a>
698602492	Wellhead leaking packing.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6745231">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6745231</a>