

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2024

Submitted Date:

10/18/2024

Document Number:

707801173

FIELD INSPECTION FORMLoc ID 335616 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286649	WELL	PR	04/01/2023	GW	045-12719	CHEVRON 13-13D	PR
286650	WELL	PR	04/01/2023	GW	045-12718	CHEVRON 13-14D	PR
286651	WELL	PR	06/01/2024	GW	045-12717	CHEVRON 13-16D	PR
293707	WELL	SI	05/01/2024	GW	045-15112	CHEVRON 33B-13R	PR
293716	WELL	PR	05/03/2008	GW	045-15113	CHEVRON 275-13	PR
293717	WELL	SI	07/01/2024	GW	045-15114	CHEVRON 13-8D	PR
293718	WELL	PR	05/01/2023	GW	045-15115	CHEVRON 13-7D	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday 10/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Chevron J13, at Location # 335616 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Chemical valve on well head leaking. Pumper fixed.
 2. 95 BBL condensate tank is open to atmosphere.
 3. Chemical tank labeling is illegible
 4. Lack of tank battery signage
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	12/20/2024
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank labeling is illegible		
Corrective Action:	Provide proper labeling	Date:	11/15/2024

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Chemical valve on well head leaking. Pumper fixed. No C/A needed		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		

Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 7	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		,
Comment:	95 BBL condensate tank is open to atmosphere.				
Corrective Action:	Eliminate wildlife access and prevent venting of condensate.				Date: 11/07/2024

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID:	286649	Type:	WELL	API Number: 045-12719 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286650	Type:	WELL	API Number: 045-12718 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	286651	Type:	WELL	API Number: 045-12717 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	293707	Type:	WELL	API Number: 045-15112 Status: SI Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	293716	Type:	WELL	API Number: 045-15113 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	293717	Type:	WELL	API Number: 045-15114 Status: SI Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	293718	Type:	WELL	API Number: 045-15115 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Gravel						
Berms						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	414674	1631359	
	414674	1631359	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801181	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6754855