

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2024

Submitted Date:

10/16/2024

Document Number:

715500835

FIELD INSPECTION FORM

Loc ID 313044	Inspector Name: Burchett, Kirby	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: ECMC Operator Number: 3975 Name of Operator: ARGALI EXPLORATION COMPANY Address: PO BOX 416 City: RANGELY State: CO Zip: 81648				Findings: 10 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rector, Brian	(970) 629-1906	brector1983@gmail.com	
Engineering, ECMC		dnr_cogccengineering@state.co.us	
, Inspections		argaliexplorationcompany@gmail.com	
Rector, Jeff	(970) 629-2614	jbrduco@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223438	WELL	PR	05/01/2023	GW	081-06804	STATE 1-31	PR

General Comment:ECMC Inspection Report Summary

On Wednesday, 10/16/2024, Inspector Kirby Burchett, conducted a routine field inspection at Argali Exploration Company on the State 1-31 well, Location #313044, in Moffat County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Relief vent riser caps missing.
2. Unused equipment.
3. Equipment open to wildlife.
4. Unmarked anchor.

Refer to Inspection Photos for observed compliance issues.

Review of production records indicate operator is delinquent in submitting monthly operations reports.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-629-1906	
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Methanol tank lacking containment		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	11/01/2024
Type	OTHER		
Comment:	Burner on separator open to wildlife		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	11/01/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Caps missing on relief vent risers		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.		Date: 10/27/2024
Type: Deadman # & Marked	# 0		
Comment:	1 unmarked		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		Date: 10/31/2024
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Unused methanol tank		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	223438	Type:	WELL	API Number:	081-06804	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	May 2024 Production Report Review of production records indicate operator is delinquent in submitting monthly operations reports.								
Corrective Action:	Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month. A Well will be reported every month from the month that it is spud until it has been reported for one month as abandoned. Each formation that is completed in a Well will be reported every month from the time that it is completed until it has been abandoned and reported for one month as abandoned. The reported volumes will include all Fluids produced during Flowback, initial testing, completion, and production of the Well.					Date:	11/16/2024		

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.				
Corrective Action:						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403960520	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6749515
715500836	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6749509