

Inspection Photos

October 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 307021

Inspection Document #: 714001378

La Plata County, CO

Township: SWNW 36 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad Ute 1-36 2
Location ID: 307021



Photo 1. View of the well pad taken from the access point facing center. Note: well sign is not reflecting current operator.



API #: 067-09575

Inspection Photos
Location Name: Bondad Ute 1-36 2
Location ID: 307021

10/22/24
71° E




Photo 2. View of the southern interim reclamation area facing west. Vegetation consists of Intermediate Wheatgrass, Smooth Brome and Sand Dropseed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09575

Inspection Photos
Location Name: Bondad Ute 1-36 2
Location ID: 307021



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. No leaks/impacted surface material observed at well head.

API #: 067-09575

Inspection Photos
Location Name: Bondad Ute 1-36 2
Location ID: 307021



Photo 4. Small patch of flowering Musk Thistle observed along the northern edge of the active pad.



Inspection Photos
Location Name: Bondad Ute 1-36 2
Location ID: 307021



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of erosion forming along existing stormwater BMPs in the northwest corner of the disturbance. Additional stabilization/BMPs are needed in this area.

API #: 067-09575

Inspection Photos
Location Name: Bondad Ute 1-36 2
Location ID: 307021



Photo 6. Reference area composed of Prickly Pear, Blue Grama and Juniper.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09575