

Inspection Photos

October 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 333541

Inspection Document #: 714001383

La Plata County, CO

Township: NWSE 14 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCarville B1
Location ID: 333541



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-07877



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: McCarville B1
Location ID: 333541



10/22/24
38° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Weedy debris on active well pad.

API #: 067-07877

Inspection Photos
Location Name: McCarville B1
Location ID: 333541

10/22/24
31° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Patch of flowering musk thistle observed along the eastern edge of the disturbance.

API #: 067-07877

Inspection Photos
Location Name: McCarville B1
Location ID: 333541



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of gully erosion observed forming in the eastern interim reclamation area.

API #: 067-07877

Inspection Photos
Location Name: McCarville B1
Location ID: 333541

10/22/24
170° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Southern interim reclamation area composed of Rubber Rabbitbrush and Sand Dropseed.

API #: 067-07877

Inspection Photos
Location Name: McCarville B1
Location ID: 333541



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area composed of Sagebrush, Purple Threeawn and Juniper.

API #: 067-07877